

**DEVELOPMENT SERVICES- BUILDING DIVISION
NIGHTCLUB INSPECTIONS REPORT
FY 2008-2009**

DATE/TIME	LOCATION/ADDRESS	RESULT	COMMENTS
07/16/2008-2:28P-2:57P	FL TATIANA CLUB-RESTAURANT, INC 1710 E. HALLANDALE BEACH BLVD	FAILED	<ul style="list-style-type: none"> 1.) 460.8 Extension cord running through door jam 2.) Extension cord to flat screen TV. 2nd floor North (strobe blocked) by TV. 3.) Light removed 2nd floor dressing room 4.) Electrical panel cover missing at 2nd floor backstage (open wiring) 5.) Open extension cords spaced 6.) Open wiring behind sound board 7.) Extension cords into ceiling space 8.) Light wire with extension cord 9.) Filler blank missing 10.) All emergency lights are not operation AC (Check battery) 11.) Remove all extension cords in kitchen and replace with approved wiring methods
07/16/2008-3:05P-3:25P	FLANNIGAN'S SEAFOOD BAR AND GRILL 4. N. FEDERAL HIGHWAY	HOLD	<ul style="list-style-type: none"> 1.) Remove extension cord to golf cart and replace with approved wiring 2.) Emergency light in men's bathroom failed to operate. Double check all emergency lights for operation *Permit and inspections for new wiring.
07/17/2008-2:25P-3:20P	GULFSTREAM PARK FOOD & BEVERAGE 901 S. FEDERAL HIGHWAY	OKAY	
07/17/2008-3:25P-3:49P	HOLLYWOOD CONCESSIONS, INC 831 N. FEDERAL HIGHWAY	OKAY	

**DEVELOPMENT SERVICES- BUILDING DIVISION
NIGHTCLUB INSPECTIONS REPORT
FY 2008-2009**

DATE/TIME	LOCATION/ADDRESS	RESULT	COMMENTS
07/17/2008-3:30P-3:58P	OCEAN'S 11 LOUNGE SOUTH 800 N. FEDERAL HIGHWAY	FAILED	1.) Trip hazard in new bar (North) floor tile broken 2.) Romex at South door to soffit lights (remove and replace) 3.) Exit light in east bar is plastered into wall remove and replace 4.) Outlets hanging out of wall 5.) Check romex plug in kitchen to bell. Under Counter 6.) Broken box and consult on floor in kitchen. repair and replace
	THE WINE CELLAR RESTAURANT 1727 E. HALLANDALE BEACH BLVD	OKAY	1.) Womens bathroom emergency light does not work