

Night Club after hours Inspection ReportElectrical

Location Name & address	Pass/fail	Comments
<i>The Cheetah</i>	Fail 12/5/14	1. Remove exit light over door between office #3 & sound room.
100 Ansin Blvd		2. Replace exit light with a combination exit/em light in the dry storage near kitchen (Rm 152)
		3. Install new exit light near stairwell #145 (near kitchen)
		4. Provide a sign stating (not an exit) at the dry storage.
		5. Acquire permit for repairs.
		6.
		7.
		8.
		9.
		10.
		11.

Night Club after hours Inspection Report

Structural

Location Name & address	Pass/fail	Comments
<i>The Cheetah</i>	Fail 12/5/14	1. Remove door and wall in hallway near dressing room or submit plan to show it to remain.
100 Ansin Blvd		2. Acquire permit to either remove wall and door or to submit new plan.
		3.
		4.
		5.
		6.
		7.
		8.
		9.
		10.
		11.